

Luis Ramos
Quality Manager
Mexicali Service Center
ED7Y210Y

**Rockwell
Collins**

Ensambladores Electronicos
de México S. de R.L. de C.V.
Av. Sierra San Agustin #2498
Col. El Porvenir C.P. 21185
Mexicali B. C. México.
Tel: (714) 929 4652
Fax: (714) 929 4601
Luis.ramos@rockwellcollins.com



Jan 23rd, 2017

FAA FSDO

Attn: FAA Aviation Safety Inspector
Mr. Jose Benavides
DFW International Field Office

Dear: Mr. Jose Benavides,

Thank you for your guidance.

The following letter is to confirm you that Ensambladores Electrónicos de México S. de R. L. de C. V.,
Certificate number ED7Y210Y currently is not contracting Maintenance Function.

In the Appendix A are listed the Vendors certified by FAA that are performing work for Ensambladores
Electrónicos de México S. de R. L. de C. V.

Sincerely,

Luis Ramos
Quality Manager/Chief Inspector
ROCKWELL COLLINS Inc.

1/23/17

Date

Luis Ramos

Quality Manager /Chief
Inspector
Mexicali Service Center
ED7Y210Y

**Rockwell
Collins**

Ensambladores Electronicos
de México S. de R.L. de C.V.
Av. Sierra San Agustin #2498
Col. El Porvenir C.P. 21185
Mexicali B. C. México.
Tel: (714) 929 4600
Fax: (714) 929 4601
Luis.ramos@rockwellcollins.com

APPENDIX A (1/3)

Vendor	Vendor Address	Phone / Fax #	Basis of Approval	FAA Certificated Rating	Work Performed
Baker Electronics, Inc. a wholly-owned subsidiary of Honeywell International Inc. VC 251013	8323 Linbergh Court Sarasota, FL. 34243	Ph: 941-360-6100 Ext. 6122 Fax: 941-355-9241	Approved on 12/07/2015	YES- Cert. No. OJ4R416M Radio (8/08/2000) Accessory (05/21/2008)	Repair Monitors (Replacing of EMI Lens, Fans, Re- soldering of connections) 1301851-100 24-622100-002
EMS Defense Technologies, Inc. (Honeywell Co.) VC 251022	660 Engineering Drive Norcross, Georgia. 30091-7700	Ph: 770-263-9200 Fax: 770-446-5739	Approved on 2/12/2016	YES- Cert. No. Q5ER195Y Limited Accessory (Electronic) Limited Radio (07/17/2014)	Repair CFS and EASU units: (Replacing of hard drives, hard drives, batts, Ethernet cable) 1303576-10X 1307308-100 1301392-101 1301398-101 1301801-100 205945-0004
Radiant Power Corp. VC 251100	7135 16 th Street East Suite 101 Sarasota, FL 34243 USA	Ph: 941-739-3200 Fax: 941-739-3201	Approved on 4/7/2016	YES- Cert. No. W9PR345Y Limited Accessory (07/20/1999) Specialized Service (06/21/2006)	Repair Power Supply of EADB (Replacing of main board and logic board) 1306761-101
United Service Applications, Inc. VC 251087	600 S. Grand Ave. Suite #108 Santa Ana California 92705, USA	Ph: 714-954-1192 Fax: 949-757-3263	Approved on 7/12/2016	YES- Cert. No. U74R497B Limited Accessory	Repair as needed (replacing parts) the following components: 128-1V08-020 1303158-100 1303500-001 1306583-003 1310463-001 270-0520-000 330-4870-005 442-0368-001 606335-0002 CPD170185 861-00008-001 900-0104-006 1310463-001 CPD140000-001 128-1V08-020 1310464-100 RV300-1063-100 RV300-1063-103 606335-0001 1307424-103 1303161-100 1302455-100 442-2327-001 RV300-1063-004 1304360-100 1304343-002 1302152-101 1302730-001 1301287-100 CPD140000-001 ACPD170186 RV700-2353-001



Luis Ramos
 Quality Manager /Chief
 Inspector
 Mexicali Service Center
 ED7Y210Y

Ensambladores Electronicos
 de México S. de R.L. de C.V.
 Av. Sierra San Agustin #2498
 Col. El Porvenir C.P. 21185
 Mexicali B. C. México.
 Tel: (714) 929 4600
 Fax: (714) 929 4601
 Luis.ramos@rockwellcollins.com

APPENDIX A (2/3)

Vendor	Vendor Address	Phone / Fax #	Basis of Approval	FAA Certificated Rating	Work Performed
United Service Applications, Inc. VC 251087 (continuation)	600 S. Grand Ave. Suite #108 Santa Ana California 92705, USA	Ph: 714-954-1192 Fax: 949-757-3263	Approved on 7/12/2016	YES- Cert. No. U74R497B Limited Accessory	Repair as needed (replacing parts) the following components: RV700-2353-001 RV330-4870-000 30-624860-002 1302160-100 1302160-101 A-8271-843-A 1308150-005 RV300-1063-006 30-624860-003 1302151-006 920722-4 920722-5 920722-6 1306583-001 1306583-002 1306583-004 1306583-005 1306583-006 1306583-007 1306583-008 1310474-100 1303161-102 1302152-100 1302152-102 1302160-103 442-0370-001
GDCA Inc. VC 252935	1799 Portola Ave. Livermore CA 94551, USA	Ph: 925-456-9900 Ext 249 Fax: 925-456-9901	Approved on 7/18/2016	YES- Cert. No. 2GCR082C L-AAC, Limited Rating - Accessory	Repair as needed (replacing parts) the following components: 921720-X
Quest International Monitor Service Inc. VC 251040	65 Parker Irvine CA 92618, USA	Ph: 949-581-9900 Fax: 949-581-4011	Approved on 9/22/2016	YES- Cert. No. QIGR622Y Limited Accessory Limited Radio	Repair as needed (replacing parts) the following components: A-8265-587-A 617-6592-002 617-6592-003 700-1429-002 1310458-106 A-8314-717-A

Denotes latest changes.



Luis Ramos
Quality Manager /Chief
Inspector
Mexicali Service Center
ED7Y210Y

Ensambladores Electronicos de
México S. de R.L. de C.V.
Av. Sierra San Agustin #2498
Col. El Porvenir C.P. 21185
Tel: (714) 929

Mexicali B. C. México.
4600

Fax: (714) 929 4601
Luis.ramos@rockwellcollins.com

APPENDIX A (3/3)

<u>Vendor</u>	<u>Vendor Address</u>	<u>Phone / Fax #</u>	<u>Basis of Approval</u>	<u>FAA Certificated Rating</u>	<u>Work Performed</u>
Techno Coatings, Inc. VC 251695	1865 N.E. 144 Street North Miami, FL 33181	Ph: 305-945-2220 Fax: 305-945-1286	Approved on 9/1/2016	YES- Cert. No. 19TR441B Limited Specialized Service	Plating
Signature Plating VC 251405	1135 Guadalupe Drive Cibolo T.X. 78108	Ph: 210-658-55-99 Fax: 210-658-99-77	Approved on 4/01/2016	YES- Cert. No. 7SGR366B Limited Airframe Limited Specialized Service	Plating
High Tech Finishing VC 251445	6201 Royalton St. Houston, T.X. 77081	Ph: 713-666-0550 x1145 Fax: 713-666-0052	Approved on 3/29/2016	YES- Cert. No. Q9HR088B Limited Specialized Service (04/17/2008)	Plating
City Plating and Metal Finishing, LLC. VC 251515	11511 Reverie San Antonio, T.X. 78216	Ph: 210-341-0772 Fax: 210-341-8874	Approved on 4/15/2016	YES- Cert. No. 2CMR246C Limited Specialized Service	Plating

Denotes latest changes.